

Date: 03/31/16

SUMMIT HELICOPTERS, INC.

Page 1

Time: 10:50:54

Maintenance Tracking Report

Aircraft Tail Number: N407TN

Description: Light single turbine helicopter

Mfr.: BELL

Model No.: 407

Serial No.: 53836

Last Flight: 03/23/16

Hours: 1435.40

Hobbs: 1435.4

Cycles: 4770

Rins: 4770

This Report is Ordered By: Item Number

Non-Calendar Items

ATA/Item Code	Item/POS.	Component Name	Part #	Serial #	— Airframe Times —			— Component Hours/Cycles —			
					Service Life	Installed/Completed At	Due At	Since New	Since Overhaul	At Installation	Remaining
		AIRFRAME FUEL FILTER		*	300RT	1388.70	1688.70	46.70	N/A	0.00	253.30
		HYDRAULIC SYSTEM		*	OC	0.00	N/A	1435.40	N/A	0.00	N/A
		Oil drain & service		*	300IN	1388.70	1688.70	46.70	N/A	0.00	253.30
		Hydraulic filter inspect		*	300IN	1388.70	1688.70	46.70	N/A	0.00	253.30
		ENGINE	250-C47B	CAE-848113	OC	1393.70	N/A	1431.30	N/A	1389.60	N/A
1	1	BLADE MR HV	407-015-001-137	A-4190	OC	0.00	N/A	1435.40	N/A	0.00	N/A
	1	BLADE MR HV	407-015-001-137	A-4186	OC	0.00	N/A	1435.40	N/A	0.00	N/A
	1	BLADE MR HV	407-015-001-137	A-4192	OC	0.00	N/A	1435.40	N/A	0.00	N/A
	1	BLADE MR HV	407-015-001-137	A-4197	OC	0.00	N/A	1435.40	N/A	0.00	N/A
2	2	HUB ASSY.	407-010-100-123	LK427	2500OH	0.00	2500.00	1435.40	1435.40	0.00	1064.60
1	2	YOKE ASSY	407-010-101-109	A-1171	OC	0.00	N/A	1435.40	N/A	0.00	N/A
2	2	GRIP ASSY	406-010-108-131	LP2364	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
	2	GRIP ASSY	406-010-108-131	LP2375	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
	2	GRIP ASSY	406-010-108-131	LP2379	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
	2	GRIP ASSY	406-010-108-131	LP2387	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
3	2	PITCH HORN ASSY	407-010-103-113	AZ1472	OC	0.00	N/A	1435.40	N/A	0.00	N/A
	2	PITCH HORN ASSY	407-010-103-113	AZ1476	OC	0.00	N/A	1435.40	N/A	0.00	N/A
	2	PITCH HORN ASSY	407-010-103-113	AZ1477	OC	0.00	N/A	1435.40	N/A	0.00	N/A
	2	PITCH HORN ASSY	407-010-103-113	AZ1483	OC	0.00	N/A	1435.40	N/A	0.00	N/A
4	2	PLATE ASSY UPPER	406-010-115-127	AZ615	2500RT	0.00	2500.00	1435.40	N/A	0.00	1064.60
5	2	PLATE ASSY LOWER	406-010-117-125	AZ484	2500RT	0.00	2500.00	1435.40	N/A	0.00	1064.60
6	2	SEAT	407-010-107-105	LK127	OC	0.00	N/A	1435.40	N/A	0.00	N/A
3	3	PITCH LINK ASSY	406-010-413-137	TH1190	OC	0.00	N/A	1435.40	N/A	0.00	N/A

Maintenance Tracking Report

Aircraft Tail Number: N407TN

Description: Light single turbine helicopter

Mfr.: BELL	Model No.: 407	Serial No.: 53836	Last Flight: 03/23/16
Hours: 1435.40	Hobbs: 1435.4	Cycles: 4770	Rins: 4770

This Report is Ordered By: Item Number

Non-Calendar Items

ATA/Item Code	Item/POS.	Component Name	Part #	Serial #	— Airframe Times —			— Component Hours/Cycles —			
					Service Life	Installed/Completed At	Due At	Since New	Since Overhaul	At Installation	Remaining
1	3	ROD END ASSY	406-310-404-105	NH14615	OC	0.00	N/A	1435.40	N/A	0.00	N/A
2	3	BEARING	406-310-405-101	RXFS23582	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
3	3	CLEVIS	406-010-416-103	TIFS1314	OC	0.00	N/A	1435.40	N/A	0.00	N/A
4	3	TUBE ASSY	406-010-413-139	VA103035	OC	0.00	N/A	1435.40	N/A	0.00	N/A
3	3	PITCH LINK ASSY	406-010-413-137	TI1196	OC	0.00	N/A	1435.40	N/A	0.00	N/A
1	3	ROD END ASSY	406-310-404-105	NH14509	OC	0.00	N/A	1435.40	N/A	0.00	N/A
2	3	BEARING	406-310-405-101	RXFS23452	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
3	3	CLEVIS	406-010-416-103	TIFS1309	OC	0.00	N/A	1435.40	N/A	0.00	N/A
4	3	TUBE ASSY	406-010-413-139	VA103045	OC	0.00	N/A	1435.40	N/A	0.00	N/A
3	3	PITCH LINK ASSY	406-010-413-137	TI1197	OC	0.00	N/A	1435.40	N/A	0.00	N/A
1	3	ROD END ASSY	406-310-404-105	NH14647	OC	0.00	N/A	1435.40	N/A	0.00	N/A
2	3	BEARING	406-310-405-101	RXFS23528	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
3	3	CLEVIS	406-010-416-103	TIFS1269	OC	0.00	N/A	1435.40	N/A	0.00	N/A
4	3	TUBE ASSY	406-010-413-139	VA103046	OC	0.00	N/A	1435.40	N/A	0.00	N/A
3	3	PITCH LINK ASSY	406-010-413-137	TI1194	OC	0.00	N/A	1435.40	N/A	0.00	N/A
1	3	ROD END ASSY	406-310-404-105	NH14671	OC	0.00	N/A	1435.40	N/A	0.00	N/A
2	3	BEARING	406-310-405-101	RXFS22189	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
3	3	CLEVIS	406-010-416-103	TIFS1268	OC	0.00	N/A	1435.40	N/A	0.00	N/A
4	3	TUBE ASSY	406-010-413-139	VA103043	OC	0.00	N/A	1435.40	N/A	0.00	N/A
	4	MAST ASSY	407-040-011-107	53836	2500OH	0.00	2500.00	1435.40	1435.40	0.00	1064.60
1	4	Mast Pole	407-040-038-111	N333	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
Comments: 12 mo insp. c/w ASB 407-11-94 for corrosion											
5	5	HUB SET	406-010-428-109	TI1062	OC	0.00	N/A	1435.40	N/A	0.00	N/A

Maintenance Tracking Report

Aircraft Tail Number: N407TN

Description: Light single turbine helicopter

Mfr.: BELL	Model No.: 407	Serial No.: 53836	Last Flight: 03/23/16
Hours: 1435.40	Hobbs: 1435.4	Cycles: 4770	Rins: 4770

This Report is Ordered By: Item Number

Non-Calendar Items

ATA/Item Code	Item/POS.	Component Name	Part #	Serial #	— Airframe Times —			— Component Hours/Cycles —			
					Service Life	Installed/Completed At	Due At	Since New	Since Overhaul	At Installation	Remaining
6	6	RING ASSY	406-010-427-109	TI493	OC	0.00	N/A	1435.40	N/A	0.00	N/A
7	7	LEVER ASSY	406-010-425-107	TI1164	OC	0.00	N/A	1435.40	N/A	0.00	N/A
	7	LEVER ASSY	406-010-425-107	TI1166	OC	0.00	N/A	1435.40	N/A	0.00	N/A
8	8	LINK ASSY	406-010-426-101	TIFS1514	OC	0.00	N/A	1435.40	N/A	0.00	N/A
	8	LINK ASSY	406-010-426-101	TIFS1531	OC	0.00	N/A	1435.40	N/A	0.00	N/A
9	9	SWPL & SUP ASSY	406-010-401-117	TI405	2500OH	0.00	2500.00	1435.40	1435.40	0.00	1064.60
1	9	OUTER RING ASSY	406-010-411-117	TI752	OC	0.00	N/A	1435.40	N/A	0.00	N/A
2	9	SLEEVE ASSY	406-010-409-113	TI575	OC	0.00	N/A	1435.40	N/A	0.00	N/A
3	9	INNER RING ASY	406-010-410-121	TI582	OC	0.00	N/A	1435.40	N/A	0.00	N/A
4	9	SUPPORT ASSY	406-010-406-119	TI565	OC	0.00	N/A	1435.40	N/A	0.00	N/A
5	9	LEVER ASSY	406-010-431-109	TI706	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
6	9	LINK ASSY	406-010-407-101	TIFS683	OC	0.00	N/A	1435.40	N/A	0.00	N/A
7	9	LEVER ASSY	406-010-408-101	TIFS662	OC	0.00	N/A	1435.40	N/A	0.00	N/A
8	9	LINK ASSY	406-010-432-101	TIFS639	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
10	10	TRANSMISSION AS	407-040-006-115	A-880	5000OH	0.00	5000.00	1435.40	1435.40	0.00	3564.60
Comments: At overhaul: c/w ASB 407-12-98 planetary pinion gear inspection.											
	10	Transmission oil & filte		*	300IN	1388.70	1688.70	46.70	N/A	0.00	253.30
11	11	CONTROLS INSTALL, CYCLIC	407-001-005-101	53836	OC	0.00	N/A	1435.40	N/A	0.00	N/A
1	11	BELLCRANK ASSY, CYCLIC L	407-001-526-109	TI623	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
2	11	BELLCRANK ASSY, COLLECTI	407-001-524-109	TI1144	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
3	11	BELLCRANK ASSY, CYCLIC L	407-001-528-105	TI567	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
4	11	SUPPORT ASSY	407-001-511-101	TI388	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
12	12	BEAM ASSY, LH	407-010-201-105	TI1455	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60

Maintenance Tracking Report

Aircraft Tail Number: N407TN

Description: Light single turbine helicopter

Mfr.: BELL

Model No.: 407

Serial No.: 53836

Last Flight: 03/23/16

Hours: 1435.40

Hobbs: 1435.4

Cycles: 4770

Rins: 4770

This Report is Ordered By: Item Number

Non-Calendar Items

ATA/Item Code	Item/ POS.	Component Name	Part #	Serial #	— Airframe Times —			— Component Hours/Cycles —			
					Service Life	Installed/Completed At	Due At	Since New	Since Overhaul	At Installation	Remaining
13	13	BEAM ASSY, RH	407-010-203-105	TI1483	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
14	14	SPRING ASSY	407-010-206-103	BP1129	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
	14	SPRING ASSY	407-010-206-103	BP1089	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
15	15	SUPPORT ASSY, SERVO ACTU	407-001-500-105	HR946	OC	0.00	N/A	1435.40	N/A	0.00	N/A
16	16	DRIVE SHAFT ASSY	407-340-310-101	KC580	2500OH	0.00	2500.00	1435.40	1435.40	0.00	1064.60
17	17	FREEWHEELING UNIT	406-040-500-143	A-6891	3000OH	0.00	3000.00	1435.40	1435.40	0.00	1564.60
18	18	ROTOR BRAKE		*	OC	0.00	N/A	1435.40	N/A	0.00	N/A
1	18	DISC BRAKE	407-340-318-101	1885	1200IN	1157.80	2357.80	1435.40	N/A	0.00	922.40
	18	DISC BRAKE	407-340-318-101	1885	12000OH	0.00	12000.00	1435.40	1435.40	0.00	10564.60
2	18	CALIPER,RTR BR	407-340-302-103	167	3000OH	0.00	3000.00	1435.40	1435.40	0.00	1564.60
	18	CALIPER,RTR BR	407-340-302-103	479	3000OH	0.00	3000.00	1435.40	1435.40	0.00	1564.60
19	19	GEARBOX ASSY T/R	406-040-400-121	A-1785	5000OH	0.00	5000.00	1435.40	1435.40	0.00	3564.60
	19	Gearbox oil change		*	300IN	1388.70	1688.70	46.70	N/A	0.00	253.30
20	20	HUB ASSY, TR	407-012-101-113	HB391	2500OH	0.00	2500.00	1435.40	1435.40	0.00	1064.60
1	20	YOKE ASSY	406-012-102-109	HBFS695	5000RT	0.00	5000.00	1435.40	N/A	0.00	3564.60
2	20	BLADE TR	406-016-100-119	A-4881	300IN	1388.70	1688.70	1435.40	N/A	0.00	253.30
		Comments: 300 hr insp: ASB 407-10-92(B) part I.									
	20	BLADE TR	406-016-100-119	A-4881	OC	0.00	N/A	1435.40	N/A	0.00	N/A
		Comments: 300 hr insp: ASB 407-10-92(B) part I.									
	20	BLADE TR	406-016-100-119	A-4886	300IN	1388.70	1688.70	1435.40	N/A	0.00	253.30
		Comments: 300 hr insp: ASB 407-10-92(B) part I.									
	20	BLADE TR	406-016-100-119	A-4886	OC	0.00	N/A	1435.40	N/A	0.00	N/A
		Comments: 300 hr insp: ASB 407-10-92(B) part I.									
21	21	START/GEN 200A	206-062-200-141	S00245XL2	1000OH	1366.60	2366.60	68.80	68.80	0.00	931.20

Maintenance Tracking Report

Aircraft Tail Number: N407TN

Description: Light single turbine helicopter

Mfr.: BELL	Model No.: 407	Serial No.: 53836	Last Flight: 03/23/16
Hours: 1435.40	Hobbs: 1435.4	Cycles: 4770	Rins: 4770

This Report is Ordered By: Item Number

Non-Calendar Items

ATA/Item Code	Item/POS.	Component Name	Part #	Serial #	— Airframe Times —			— Component Hours/Cycles —			
					Service Life	Installed/Completed At	Due At	Since New	Since Overhaul	At Installation	Remaining
22	22	TAILBOOM ASSY	407-030-801-205	53836	300IN	1388.70	1688.70	1435.40	N/A	0.00	253.30
Comments: Additional inspection req. due at 6900 & 8600 hrs TSN. Ref. BHT-407-MM-1 Fig. 4-5.											
	22	TAILBOOM ASSY	407-030-801-205	53836	OC	0.00	N/A	1435.40	N/A	0.00	N/A
Comments: Additional inspection req. due at 6900 & 8600 hrs TSN. Ref. BHT-407-MM-1 Fig. 4-5.											
50	50	LUBE: SWASHPLATE BRGS &		*	50IN	1430.60	1480.60	4.80	N/A	0.00	45.20
	50	LUBE: T/R DRIVESHAFT SPL		*	150IN	1388.70	1538.70	46.70	N/A	0.00	103.30
Comments: 150 hrs allowed by TB 407-02-35 part IV-B											
	50	LUBE: T/R PITCH CHANGE M		*	300IN	1430.60	1730.60	4.80	N/A	0.00	295.20
	50	LUBE: HYDRAULIC PUMP DRI		*	300IN	1388.70	1688.70	46.70	N/A	0.00	253.30
Bulletin	2004-10-07	AD			300HR	1388.70	1688.70	N/A	N/A	N/A	253.30
Bull. Description: (b) T/R hanger & oil cooler bearings, p/n 407-340-339-107, inspect & lube. Ref. ASB 407-04-63(B) & AMOC dated 8-22-06.											
	2012-18-09	AD			300HR	1388.70	1688.70	N/A	N/A	N/A	253.30
Bull. Description: Tailboom attachment hardware torque check. Part 3 recurring inspection.											
	2013-12-07	AD			300HR	1388.70	1688.70	N/A	N/A	N/A	253.30
Bull. Description: Tailboom assembly, p/n 407-030-801-201/-203/-205, inspection. Ref. ASB 407-08-84 part II.											
	2013-12-07_I	AD			6900HR	0.00	6900.00	N/A	N/A	N/A	5464.60
Bull. Description: Tailboom assembly p/n 407-030-801-201/-203/-205. Ref. part 1 and ASB 407-08-84 part IV.											
	2013-12-07_II	AD			8600HR	0.00	8600.00	N/A	N/A	N/A	7164.60
Bull. Description: Tailboom assembly p/n 407-030-801-201/-203/-205. Ref. part 2 and ASB 407-08-84 part III.											
	2015-05-04	AD			150HR	1388.70	1538.70	N/A	N/A	N/A	103.30
Bull. Description: Upper left longeron inspection. Ref. ASB 407-11-95(C) part II.											
	407-14-106	IL			150HR	1388.70	1538.70	N/A	N/A	N/A	103.30
Bull. Description: Driveshaft mounted pulley & drive ring installation inspection. Ref. ACC SB 407-300-1(D) part 2.											

Maintenance Tracking Report

Aircraft Tail Number: N407TN

Description: Light single turbine helicopter

Engine #1

Mfr.: ROLLS ROYCE	Model No.: 250-C47B	Serial No.: CAE-848113	Last Flight: 03/23/16
Hours: 1431.30	Cycles: 1969.0		

This Report is Ordered By: Item Number

Non-Calendar Items

ATA/Item Code	Item/POS.	Component Name	Part #	Serial #	Engine Times			Component Hours/Cycles			
					Service Life	Installed/Completed At	Due At	Since New	Since Overhaul	At Installation	Remaining
1	1	COMPRESSOR	23065593	CAC-45762	2000IN	1384.60	3384.60	1431.30	N/A	0.00	1953.30
	1	COMPRESSOR	23065593	CAC-45762	OC	0.00	N/A	1431.30	N/A	0.00	N/A
	1	Impeller	23065591	JY104658	15000CY:RT	0.0	15000.0	1969.0	N/A	0.0	13031.00
	1	Impeller	23065591	JY104658	7500RT	0.00	7500.00	1431.30	N/A	0.00	6068.70
2	2	GEARBOX	23063393	CAG-48113	OC	0.00	N/A	1431.30	N/A	0.00	N/A
3	3	TURBINE	M250-10557	CAT-45296	2000OH	1384.60	3384.60	1431.30	46.70	0.00	1953.30
1	3	#1 WHEEL	M250-10227	X618985	3000CY:RT	1908.0	4908.0	61.0	N/A	0.0	2939.00
	3	#1 WHEEL	M250-10227	X618985	2025RT	1384.60	3409.60	46.70	N/A	0.00	1978.30
2	3	#2 WHEEL	M250-10658	X632927	3000CY:RT	1908.0	4908.0	61.0	N/A	0.0	2939.00
	3	#2 WHEEL	M250-10658	X632927	2025RT	1384.60	3409.60	46.70	N/A	0.00	1978.30
3	3	#3 WHEEL	23092511	X565719	6000CY:RT	0.0	6000.0	1969.0	N/A	0.0	4031.00
	3	#3 WHEEL	23092511	X565719	4550RT	0.00	4550.00	1431.30	N/A	0.00	3118.70
4	3	#4 WHEEL	23066744	X570685	6000CY:RT	0.0	6000.0	1969.0	N/A	0.0	4031.00
	3	#4 WHEEL	23066744	X570685	4550RT	0.00	4550.00	1431.30	N/A	0.00	3118.70
	4	FADEC (ECU)	M250-10695	JG07ANU1092	OC	0.00	N/A	1431.30	N/A	0.00	N/A
5	5	HMU	23078029	JGALM1223	2500OH	0.00	2500.00	1431.30	1431.30	0.00	1068.70
6	6	NOZZLE ASSY	23077067	VN1ART1347	2000OH	0.00	2000.00	1431.30	1431.30	0.00	568.70
7	7	BLEED VALVE	23073353	FF44134	1500OH	1366.60	2866.60	1431.30	64.70	0.00	1435.30

Date: 03/31/16

SUMMIT HELICOPTERS, INC.

Time: 10:50:54

Maintenance Tracking Report

Aircraft Tail Number: N407TN

Description: Light single turbine helicopter

Auxiliary System #1

Mfr.: BELL	Model No.: 407	Serial No.: 53836	Last Flight: 03/23/16
Hours: 2.80	Cycles: 5	Rins: 0	

This Report is Ordered By: Item Number

Non-Calendar Items

ATA/Item Code	Item/POS.	Component Name	Part #	Serial #	Service Life	—Aux. Sys. Times —		—————Component Hours/Cycles —————			
						Installed/Completed At	Due At	Since New	Since Overhaul	At Installation	Remaining
1	1	BELL 407 CARGO HOOK SUSP	200-329-00		100IN	0.00	100.00	2.80	N/A	0.00	97.20
Comments: Inspect & Overhaul ref. OnBoard ICA 123-032-00 section 5.1											
	1	BELL 407 CARGO HOOK SUSP	200-329-00		1000OH	0.00	1000.00	2.80	2.80	0.00	997.20
Comments: Inspect & Overhaul ref. OnBoard ICA 123-032-00 section 5.1											
2	2	ONBOARD TALON	528-029-00	00612	100IN	0.00	100.00	2.80	N/A	0.00	97.20
Comments: Inspect & overhaul ref. OnBoard CMM 122-017-00 sections 4.3 & 7.0 respectively											
	2	ONBOARD TALON	528-029-00	00612	1000OH	0.00	1000.00	2.80	2.80	0.00	997.20
Comments: Inspect & overhaul ref. OnBoard CMM 122-017-00 sections 4.3 & 7.0 respectively											

Maintenance Tracking Report

Aircraft Tail Number: N407TN

Description: Light single turbine helicopter

This Report is Ordered By: Item Number

Calendar Items

ATA/Item Code	Item/ POS.	Component Name	Part #	Serial #	Service Life	Date Last Installed/ Complied/Completed	Date To Be Removed/Completed	Action To Be Taken	Days To Go
HYDRAULIC SYSTEM									0
		Oil drain & service		*	12MO	08/15/2015	08/31/2016	Inspect	153
		Hydraulic filter inspect		*	12MO	08/15/2015	08/31/2016	Inspect	153
RADIO ALTIMETER									389
Comments: §135.160 After April 24, 2017, no person may operate a rotorcraft unless it is equipped with an operable FAA-approved radio altimeter, or an FAA-approved device that incorporates a radio altimeter, unless otherwise authorized in the certificate holder's approved minimum equipment list.									
4	4	MAST ASSY	407-040-011-107	53836	60MO	02/15/2013	02/28/2018	Inspect	699
1	4	Mast Pole	407-040-038-111	N333	12MO	08/01/2015	08/31/2016	Inspect	153
Comments: 12 mo insp. c/w ASB 407-11-94 for corrosion									
10	10	TRANSMISSION AS	407-040-006-115	A-880	60MO	02/15/2013	02/28/2018	Inspect	699
Comments: At overhaul: c/w ASB 407-12-98 planetary pinion gear inspection.									
	10	Transmission oil & filte		*	12MO	08/15/2015	08/31/2016	Inspect	153
17	17	FREEWHEELING UNIT	406-040-500-143	A-6891	60MO	02/15/2013	02/28/2018	Inspect	699
19	19	GEARBOX ASSY T/R	406-040-400-121	A-1785	60MO	02/15/2013	02/28/2018	Inspect	699
	19	Gearbox oil change		*	12MO	08/15/2015	08/31/2016	Inspect	153
25	25	ELT		*	12MO	08/15/2015	08/31/2016	Inspect	153
	25	ELT Battery		*	60MO	07/15/2012	07/31/2017	Retire	487
26	26	STATIC SYSTEM			24MO	01/20/2016	01/31/2018	Inspect	671
27	27	TRANSPONDER		*	24MO	01/20/2016	01/31/2018	Inspect	671
50	50	LUBE: SWASHPLATE BRGS &		*	3MO	03/15/2016	06/30/2016	Inspect	91
	50	LUBE: T/R PITCH CHANGE M		*	3MO	03/15/2016	06/30/2016	Inspect	91
	50	LUBE: HYDRAULIC PUMP DRI		*	12MO	08/15/2015	08/31/2016	Inspect	153
100	100	FIRE EXTINGUISHER		X-724547	144MO	08/15/2015	08/31/2027	Service	4170
	100	Fire Extinguisher condit		*	30DY	02/15/2016	03/16/2016	Inspect	-15

Date: 03/31/16

SUMMIT HELICOPTERS, INC.

Page 9

Time: 10:50:54

Maintenance Tracking Report

Aircraft Tail Number: N407TN

Description: Light single turbine helicopter

This Report is Ordered By: Item Number

Calendar Items

ATA/Item Code	Item/POS.	Component Name	Part #	Serial #	Service Life	Date Last Installed/Complied/Completed	Date To Be Removed/Completed	Action To Be Taken	Days To Go
100		Fire Extinguisher condit		*	12MO	02/15/2016	02/15/2017	Inspect	321
Bulletin	407-14-114		TB			10/19/2015	08/30/2016		152
Bull. Description: Engine aft combustion drain valve, removal. Perform at customer's option.									
Auxiliary System #1 Components									
1	1	BELL 407 CARGO HOOK SUSP	200-329-00		365DY	11/11/2015	11/10/2016	Inspect	224
Comments: Inspect & Overhaul ref. OnBoard ICA 123-032-00 section 5.1									
	1	BELL 407 CARGO HOOK SUSP	200-329-00		60MO	09/04/2015	09/30/2020	Overhaul	1644
Comments: Inspect & Overhaul ref. OnBoard ICA 123-032-00 section 5.1									
2	2	ONBOARD TALON	528-029-00	00612	365DY	11/11/2015	11/10/2016	Inspect	224
Comments: Inspect & overhaul ref. OnBoard CMM 122-017-00 sections 4.3 & 7.0 respectively									
	2	ONBOARD TALON	528-029-00	00612	60MO	05/23/2012	05/31/2017	Overhaul	426
Comments: Inspect & overhaul ref. OnBoard CMM 122-017-00 sections 4.3 & 7.0 respectively									

Date: 03/31/16

SUMMIT HELICOPTERS, INC.

Time: 10:50:54

Maintenance Tracking Report

Aircraft Tail Number: N407TN

Description: Light single turbine helicopter

This Report is Ordered By: Item Number

Retirement Index Number Items

ATA/Item Code	Item/POS.	Component Name	Part #	Serial #	Service Life	Hours Remaining	R.I.N. Factor	Current R.I.N.	R.I.N. At Installation	R.I.N. Remaining
2		HUB ASSY.								
7	2	DRIVE RING SET	406-010-126-113	LK406	100000RIN	N/A	1.00	4770.00	0.00	95230.00
4	4	MAST ASSY								
Comments: 12 mo insp. c/w ASB 407-11-94 for corrosion										
1	4	Mast Pole	407-040-038-111	N333	18000RIN	3564.60	1.00	4770.00	0.00	13230.00
12	12	BEAM ASSY, LH	407-010-201-105	TI1455	17000RIN	3564.60	1.00	4770.00	0.00	12230.00
13	13	BEAM ASSY, RH	407-010-203-105	TI1483	17000RIN	3564.60	1.00	4770.00	0.00	12230.00
23	23	FWD CROSSTUBE	407-724-101	5552	5000RIN	N/A	0.00	0.00	0.00	5000.00
Comments: Run on landings only!!! Ref. AD2005-03-07(1)(c)										
24	24	AFT CROSSTUBE	407-725-106	835	5000RIN	N/A	0.00	0.00	0.00	5000.00
Comments: Run on landings only!!! Ref. AD2005-03-07(1)(c)										